

PURPLE GLITZY GLITTER PLANT POTS

Give your plant pots some glittery sparkle by following these 4 easy steps.

With Rust-Oleum's Glitter Spray Paint, it's never been easier to add glittery sparkle to your project. Follow these 4 easy steps for a mess free application.

ITEMS

- Rust-Oleum Glitter Spray Paint in Purple
- Rust-Oleum Glitter Clear Sealer
- Ultra Cover 2X Spray Paint in Purple
- Plant Pots
- Drop Cloth
- Clean Lint Free Cloth
- Soil and Plants

1. PREPARE: Always work in a well-ventilated area and use a drop cloth to protect from overspray. Clean the inside and outside of the plant pots with a lint-free cloth.

2. PAINT: Shake can of Rust-Oleum Glitter spray paint for 1 minute after the mixing ball begins to rattle. Hold can upright 12-14" from surface and spray in a steady back-and-forth motion, slightly overlapping each stroke. Apply two or more light coats a few minutes apart. Allow paint to dry for approximately 20 minutes.

Tip: For a more vibrant Glitter coat spray the plant pots with two coats of Purple spray paint before applying the Glitter coat. We recommend using Ultra Cover 2X Spray in Purple.

3. PROTECT: Allow Glitter Spray Paint to dry for approximately 20 minutes, and then shake can of Rust-Oleum Glitter Clear Sealer for 1 minute after the mixing ball begins to rattle. Hold can upright 12-14" from surface and spray in a steady back-and-forth motion, slightly overlapping each stroke. Apply two or more light coats a few minutes apart.

4. FINISH: Allow your pots to dry for approximately 24 hours. Once completely dry fill with soil and plants and put out under good lighting and enjoy the sparkles!



As shown Rust-Oleum Glitter Spray Paint in Purple, Glitter Clear Sealer & Ultra Cover 2X Spray Paint in Purple

 **RUST-OLEUM®**

Visit www.homedepot.com/rustoleum for other great ideas, products and inspiration.